

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Thursday, March 1, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Timber Mats being staged off Division Street.



2. Talmadge Creek Staging area near MP0.75 observed area was demobilized and restored.





3. Timber mat road removed and restoration work observed near MP1.1 along Talmadge Creek.



4. Frac-City Soil Cells A & B.





5. Frac-City Soil Cells A & B.



6. Frac-City observed a Jon Boat being decontaminated.





**7. Talmadge Creek near MP1.75 timber mats removed and restoration work observed.**



**8. Talmadge Creek turbidity control structure.**





9. Overview of Talmadge Creek work.



10. Talmadge Creek near MP1.9 excavation work observed.





11. Talmadge Creek near MP1.9 excavation work observed.



12. Overview of Confluence work.





13. Overview of Confluence work.



14. Overview of Confluence work.





15. Overview of Confluence work, observed sheet piling being installed.



16. Overview of Confluence work.





**17. Overview of Confluence work.**



**18. MP2.75 RI crew observed.**






19. OB8.97 I and OB9.10 LDB scrape locations.



20. OB8.97I sheen observed in scraped area.





21. OB8.97I sheen observed in scraped area.



22. OB8.97I sheen observed in scraped area.





**23. OB10.37 RDB scrape location.**



**24. MP10.75 LDB flooding.**





**25. OB13.4 LDB excavation location.**



**26. Morrow Lake Delta.**